



Accessories:

- 219690 USB service cable for PC
- 219980SP Connection cable for MI70 Hand-Held Indicator
- 226476 Loop-powered display 4...20 mA / -80...20 °C Tdf, Nokeval 301
- 234759 Loop-powered display 4...20 mA / -80...20 °C Tdf with relays, Nokeval 302
- 218773 Plug kit (ISO 1/2")
- 222507 Plug kit (NPT 1/2")